

# Quality Control Analysis of Wood Pellet Products at PT XYZ Using the Seven Tools and New Seven Methods

### Ahmad Habib Ramadhani<sup>1</sup>\*, Isna Nugraha<sup>2</sup>

<sup>1</sup>Progam Studi Teknik Industri, Fakultas Teknik dan Sains, Universitas Pembangunan Nasional Veteran Jawa Timur

### \*Corresponding Author: 21032010049@student.upnjatim.ac.id1

| Article history:  | ABSTRACT   |
|---|--|
| Received: 4 January 2025<br>Accepted: 13 January 2025<br>Published: 13 January 2025 | Quality is a factor that determines the success of a product in<br>market competition. PT XYZ, which produces wood pellets,<br>is experiencing problems related to the quality of its products.<br>The company wants to control the quality of its products in   |
| <i>Keywords:</i><br>Quality;<br>Wood Pellet;<br>Seven Tools;<br>New Seven Tools     | order to reduce losses due to product defects. Product quality<br>control is carried out using the seven tools method to<br>determine the causes of defects and the new seven tools<br>method which is used to see the corrective actions that must<br>be taken based on the factors that cause product defects. The<br>results showed that there are 3 types of defects in wood pellet<br>products, namely water content that is too high, less density,<br>and shape that is too small. From the total amount of 12,782<br>kg of defective products, 34.24% of them are the types of<br>defects of too high moisture content, 30.50% defects of<br>insufficient density, and 35.26% defects of too small shapes.<br>The proposed improvements to prevent errors that can cause<br>product defects can be done by tightening the implementation<br>of company SOPs, improving worker performance and skills,<br>optimizing machine performance, and improving the quality<br>of the raw materials used. |

## **INTRODUCTION**

The development of the times forces a company both in the field of services and manufacturing to enter the era of globalization, required to improve the quality of services or products in order to maintain competition with other companies. The emergence of industrial development on a large and small scale both private companies and companies managed by the state will be a milestone that will advance the nation [1]. This is in line with what was conveyed by [2] that Indonesia is one of the developing countries in the world that requires massive development to support infrastructure and improve the people's economy.

One of the companies that experience challenges related to quality issues is PT XYZ. PT XYZ is a company engaged in manufacturing that produces wood pellets. According to [3] wood pellets are an alternative fuel made from wood waste, is one of the renewable fuels that is environmentally friendly has a cylindrical shape and hard. The problem faced by the company is the occurrence of defects in the products produced. Defects that occur in wood pellet products include moisture content that is too high, density and shape that is too small. The defect problem causes losses for the company because defective products cannot be sold. Therefore, PT XYZ needs an appropriate quality control method to overcome these problems.

To maintain the quality of products produced by PT XYZ, it is necessary to control the quality of the products produced. Quality control is an effort to maintain the quality or quality of the goods produced, so that it is in accordance with the product specifications that have been determined based on the company's leadership policy [4]. The methods used to control process stability and control production quality are the seven tools method and the new seven tools. According to [2] the seven tools method is a statistical tool to find the root cause of quality problems so as to control quality. While the new seven tools method is a tool in mapping problems in a structured manner, to help improve production quality. Quality control with the seven tools method can be analyzed using Microsoft Excel software to process existing defect data.

The quality control process is a very necessary step in maintaining the quality of a product. Based on research conducted by [5] related to the application of the seven tools method to minimize consumer returns at PT XYZ. To complement the application of quality control, this research applies quality control using the seven tools method to determine the causes of defects and the new seven tools method which is used to see the corrective actions that must be taken based on the factors that cause product defects. Researchers want to identify the types of defects in wood pellet products, find out how much defect rate or presentation of each type of defect that occurs in wood pellet products, and then determine the proposed improvements or preventive actions that can be taken to reduce defective wood pellet products.

### MATERIALS AND METHODS

This research was conducted at PT XYZ which is located at Jl. Kandangan, Ngepeh, Rejoagung, Ngoro District, Jombang Regency, East Java. Data collection was carried out by observing the production area, then continued with secondary data collection through interviews and documentation conducted in November 2024 by taking data on wood pellet production defects from August 2024 to November 2024. The dependent variable in this research is the number of wood pellet products produced by PT XYZ that have defects. While the dependent variable in this research is the type of defect in wood pellet products such as too high moisture content, less product density, and the shape of the product is too small. The population of this research itself includes all wood pellet production results at PT XYZ in August - November 2024.

Identification from the beginning was carried out to map the problems until the proposed improvements were formulated using the seven tools method and the new seven tools. The first data processing is done using tools from the seven tools method to find out the causes of defects, the seven tools method basically consists of seven control tools including check sheets, histograms, scatter diagrams, stratification, pareto diagrams, control charts, fishbone [6]. Then further analysis is carried out to see the corrective actions that must be taken based on the factors that cause product defects using the new seven tools method, where the tools used are affinity diagrams, tree diagrams, arrow diagrams, process decision program charts (PDPC), relationship diagrams, matrix diagrams, and matrix data analysis [7].

The steps in this research begin with field studies and literature studies. Then the formulation of existing problems in the company is carried out, determining the objectives of the research, and identifying operational variables. After that, data collection is carried out which includes production process data, types of defects, and the number of defects. The data is then processed using the seven tools method and the new seven tools with the help of Microsoft Excel software. The results of data processing are used in making conclusions from the research.

## **RESULTS AND DISCUSSIONS**

## Results

Seven Tools Data Processing

Data processing using the seven tools method is analyzed with tools such as check sheets, data stratification, histograms, scatter diagrams, control charts, pareto diagrams, and fishbone diagrams.

1. Check Sheet

A Check Sheet is a simply designed sheet that lists things that are necessary for data recording purposes so that users can collect data easily, systematically and in an organized manner. [8]. The following is a check sheet table at PT XYZ :

|       | CHECK SHEET            |        |           |         |          |         |  |  |  |  |  |
|-------|------------------------|--------|-----------|---------|----------|---------|--|--|--|--|--|
| No.   | Defect Type            |        | Mor       | nth     |          | T- (-1  |  |  |  |  |  |
| INO.  | Defect Type            | August | September | October | November | - Total |  |  |  |  |  |
| 1     | Too high water content | 1122   | 1157      | 1129    | 969      | 4377    |  |  |  |  |  |
| 2     | Density                | 937    | 852       | 1147    | 962      | 3898    |  |  |  |  |  |
| 4     | Too Small Shape        | 1064   | 947       | 1434    | 1062     | 4507    |  |  |  |  |  |
| Total |                        | 3123   | 2956      | 3710    | 2993     |         |  |  |  |  |  |

It can be seen in Table 1. that the data used in this research includes data on the types of defects, namely too high moisture content, density, and too small a shape as well as production data from August to November.

## 2. Data Stratification

Stratification is a table that classifies problems (in this case defects) into several groups [9]. This research categorizes defective products into the types of defects.

|       | STRATIFICATION         |               |                       |                              |  |  |  |  |  |
|-------|------------------------|---------------|-----------------------|------------------------------|--|--|--|--|--|
| NO.   | Defect Type            | Quantity (kg) | Defect Percentage (%) | Cumulative<br>Percentage (%) |  |  |  |  |  |
| 1     | Too High Water Content | 4377          | 34,24%                | 34,24%                       |  |  |  |  |  |
| 2     | Density                | 3898          | 30,50%                | 64,74%                       |  |  |  |  |  |
| 3     | Too Small Shape        | 4507          | 35,26%                | 100,00%                      |  |  |  |  |  |
| Total |                        | 12782         | 100,00%               |                              |  |  |  |  |  |

 Table 2. Stratification of Wood Pellet Defects

It can be seen in table 2. explaining about the types of defects or defects that are most in the form of too small as much as 4507 kg, too high water content as much as 4377 kg, and less density as much as 3898 kg. Besides that it can also be seen the percentage of defects that occur in wood pellet products.

## 3. Histogram

Histogram is a tool that helps to determine variation in the process. In the form of bar charts that show tabulations of data organized by size [10]. The types of defects on the check sheet are then recapitulated and presented in the form of a histogram.




Figure 2. Histogram of Wood Pellet Defects

It can be seen in Figure 2. explaining about the types of defects or defects that are most in the form of too small as much as 4507 kg, too high water content as much as 4377 kg, and less density as much as 3898 kg.

4. Pareto Diagram

Pareto diagram is a tool that can help identify and prioritize problems by ranking them based on their level of importance [11].

| NO. | Defect Type            | Quantity<br>(kg) | Defect Percentage (%) | Cumulative Percentage (%) |
|-----|------------------------|------------------|-----------------------|---------------------------|
| 1   | Too High Water Content | 4377             | 34,24%                | 34,24%                    |
| 2   | Density                | 3898             | 30,50%                | 64,74%                    |
| 3   | Too Small Shape        | 4507             | 35,26%                | 100,00%                   |
|     | Total                  | 12782            | 100,00%               |                           |

Table 3. Dominant Defect Identification Calculation

It can be seen in table 3. that the type of defect is dominated by shapes that are too small. Of the total number of defects of 12782 kg, 34.24% are defects of too high moisture content, 30.50% of less density, and 35.26% of too small shapes




Figure 3. Pareto Diagram of Wood Pellet Defects

It can be seen in Figure 3. that the type of defect is dominated by shapes that are too small. Of the total number of defects of 12782 kg, 34.24% are defects of too high moisture content, 30.50% of insufficient density, and 35.26% of too small shapes. 5. Scatter diagram

A scatter diagram is a graph that displays the relationship between two variables whether the relationship between them is strong or not, including process factors that affect the process and product quality [12].

## a. High Water Content Scatter Diagram




Figure 4. Scatter Diagram of High Water Content Defects

It can be seen in Figure 4. that the high water content has an even distribution of points. However, there are some points that are far from the center line of the average number of defects. These points indicate that there are many errors in production. It is also known that the distribution diagram above has the equation y = 0.128x + 36.734 with  $R^2 = 0.0134$ .




Figure 5. Scatter Diagram of Density Defects

It can be seen in Figure 5. that the density of wood pellet has an even distribution of points. However, there are some points that are far from the center line of the average number of defects. These points indicate that there are many errors in production. It is also known that the distribution diagram above has the equation y = 0.028x + 36.864 with  $R^2 = 0.0005$ .

c. Too Small Shape Diagram

b.




Figure 6. Scatter Diagram of Too Small Shape Defects

It can be seen in Figure 6. that the undersized shape has an even distribution of points. However, there are some points that are far from the center line of the average number of defects. These points indicate that there are many errors in production. It is also known that the distribution diagram above has the equation y = -0.115x + 49.735 with  $R^2 = 0.0058$ .

# 6. Control Chart

The P control chart is used to see the upper control limit and the lower control limit. If the data is still within the control limit, the data is declared controlled [13].

## a. Control Chart Calculation

| Table 4 | 1 Def           | ect Con | trol C | hart  |
|---------|-----------------|---------|--------|-------|
| raute - | $\dagger$ . DUN |         |        | iiaii |


|    | Table 4. Defect Control Chart       The Lot     Defect Type |               |          |            |       |            |                   | UCI      |        |       |
|----|---|---------------|----------|------------|-------|------------|-------------------|----------|--------|-------|
|    | I ne Lo   | t<br>d        | Too High | elect Type | Тоо   | Proportion | <u>3σ</u> =       | UCL<br>= | LCL=   |       |
| No | Observation   | u<br>(defect) |          | Density    | Small | (p=d/n)    | 3√ <u>((p</u> (1- | p+3      | p-3σ   | CL    |
|    | (n) (kg)  | (kg)          | Content  | Density    | Shape | ч ,        | p_)/n)            | σ        | 1      |       |
| 1  | 3700  | 34            | 43       | 25         | 53    | 0,009      | 0,006             | 0,021    | -0,009 | 0,015 |
| 2  | 3200  | 63            | 48       | 35         | 30    | 0,020      | 0,006             | 0,021    | -0,008 | 0,015 |
| 3  | 4500  | 85            | 47       | 83         | 33    | 0,019      | 0,005             | 0,020    | -0,009 | 0,015 |
| 4  | 3200  | 51            | 40       | 35         | 22    | 0,016      | 0,006             | 0,021    | -0,008 | 0,015 |
| 5  | 3100  | 49            | 50       | 33         | 44    | 0,016      | 0,006             | 0,021    | -0,008 | 0,015 |
| 6  | 3090  | 53            | 60       | 31         | 34    | 0,017      | 0,007             | 0,021    | -0,008 | 0,015 |
| 7  | 3480  | 40            | 36       | 42         | 19    | 0,011      | 0,006             | 0,021    | -0,009 | 0,015 |
| 8  | 3370  | 45            | 34       | 72         | 26    | 0,013      | 0,006             | 0,021    | -0,009 | 0,015 |
| 9  | 3450  | 42            | 64       | 29         | 64    | 0,012      | 0,006             | 0,021    | -0,009 | 0,015 |
| 10 | 3100  | 40            | 31       | 19         | 34    | 0,013      | 0,006             | 0,021    | -0,008 | 0,015 |
| 11 | 2940  | 56            | 32       | 43         | 37    | 0,019      | 0,007             | 0,021    | -0,008 | 0,015 |
| 12 | 3430  | 21            | 31       | 43         | 91    | 0,006      | 0,006             | 0,021    | -0,009 | 0,015 |
| 13 | 3550  | 73            | 64       | 39         | 38    | 0,021      | 0,006             | 0,021    | -0,009 | 0,015 |
| 14 | 3820  | 34            | 34       | 31         | 39    | 0,009      | 0,006             | 0,021    | -0,009 | 0,015 |
| 15 | 2800  | 52            | 43       | 27         | 39    | 0,019      | 0,007             | 0,022    | -0,008 | 0,015 |
| 16 | 3050  | 60            | 37       | 30         | 41    | 0,020      | 0,007             | 0,021    | -0,008 | 0,015 |
| 17 | 3100  | 48            | 39       | 33         | 35    | 0,015      | 0,006             | 0,021    | -0,008 | 0,015 |
| 18 | 2950  | 61            | 46       | 39         | 29    | 0,021      | 0,007             | 0,021    | -0,008 | 0,015 |
| 19 | 3120  | 54            | 35       | 43         | 33    | 0,017      | 0,006             | 0,021    | -0,008 | 0,015 |
| 20 | 3210  | 66            | 40       | 29         | 36    | 0,021      | 0,006             | 0,021    | -0,008 | 0,015 |
| 21 | 3200  | 35            | 30       | 26         | 43    | 0,011      | 0,006             | 0,021    | -0,008 | 0,015 |
| 22 | 4150  | 45            | 40       | 29         | 65    | 0,011      | 0,006             | 0,020    | -0,009 | 0,015 |
| 23 | 3700  | 62            | 50       | 27         | 46    | 0,017      | 0,006             | 0,021    | -0,009 | 0,015 |
| 24 | 2850  | 54            | 53       | 46         | 35    | 0,019      | 0,007             | 0,022    | -0,008 | 0,015 |
| 25 | 2600  | 42            | 64       | 29         | 64    | 0,016      | 0,007             | 0,022    | -0,008 | 0,015 |
| 26 | 3400  | 40            | 31       | 19         | 34    | 0,012      | 0,006             | 0,021    | -0,009 | 0,015 |
| 27 | 3100  | 31            | 72       | 43         | 61    | 0,010      | 0,006             | 0,021    | -0,008 | 0,015 |
| 28 | 4300  | 39            | 82       | 25         | 76    | 0,009      | 0,006             | 0,020    | -0,009 | 0,015 |
| 29 | 3600  | 62            | 55       | 35         | 79    | 0,017      | 0,006             | 0,021    | -0,009 | 0,015 |
| 30 | 2900  | 20            | 34       | 65         | 36    | 0,007      | 0,007             | 0,021    | -0,008 | 0,015 |
| 31 | 2750  | 43            | 37       | 24         | 46    | 0,016      | 0,007             | 0,022    | -0,008 | 0,015 |
| 32 | 3200  | 34            | 31       | 24         | 29    | 0,011      | 0,006             | 0,021    | -0,008 | 0,015 |
| 33 | 2900  | 61            | 97       | 26         | 30    | 0,021      | 0,007             | 0,021    | -0,008 | 0,015 |
| 34 | 3200  | 79            | 64       | 24         | 30    | 0,025      | 0,006             | 0,021    | -0,008 | 0,015 |
| 35 | 3100  | 49            | 96       | 42         | 60    | 0,016      | 0,006             | 0,021    | -0,008 | 0,015 |
| 36 | 2800  | 40            | 36       | 42         | 19    | 0,014      | 0,007             | 0,022    | -0,008 | 0,015 |

| 37 | 3000 | 45 | 34 | 72 | 26 | 0,015 | 0,007 | 0,021 | -0,008 | 0,015 |
|----|------|----|----|----|----|-------|-------|-------|--------|-------|
| 38 | 3100 | 63 | 35 | 85 | 24 | 0,020 | 0,006 | 0,021 | -0,008 | 0,015 |
| 39 | 3050 | 33 | 36 | 23 | 20 | 0,011 | 0,007 | 0,021 | -0,008 | 0,015 |
| 40 | 3200 | 58 | 37 | 21 | 94 | 0,018 | 0,006 | 0,021 | -0,008 | 0,015 |
| 41 | 2950 | 53 | 83 | 22 | 34 | 0,018 | 0,007 | 0,021 | -0,008 | 0,015 |
| 42 | 2755 | 48 | 34 | 28 | 20 | 0,017 | 0,007 | 0,022 | -0,008 | 0,015 |
| 43 | 3600 | 61 | 31 | 27 | 34 | 0,017 | 0,006 | 0,021 | -0,009 | 0,015 |
| 44 | 2960 | 23 | 30 | 26 | 36 | 0,008 | 0,007 | 0,021 | -0,008 | 0,015 |
| 45 | 2950 | 45 | 32 | 25 | 34 | 0,015 | 0,007 | 0,021 | -0,008 | 0,015 |
| 46 | 4500 | 56 | 33 | 34 | 32 | 0,012 | 0,005 | 0,020 | -0,009 | 0,015 |
| 47 | 3200 | 64 | 33 | 32 | 37 | 0,020 | 0,006 | 0,021 | -0,008 | 0,015 |
| 48 | 4100 | 55 | 64 | 39 | 38 | 0,013 | 0,006 | 0,020 | -0,009 | 0,015 |
| 49 | 2500 | 34 | 34 | 31 | 39 | 0,014 | 0,007 | 0,022 | -0,008 | 0,015 |
| 50 | 3000 | 39 | 37 | 37 | 13 | 0,013 | 0,007 | 0,021 | -0,008 | 0,015 |
| 51 | 3000 | 54 | 38 | 36 | 34 | 0,018 | 0,007 | 0,021 | -0,008 | 0,015 |
| 52 | 3100 | 57 | 31 | 28 | 64 | 0,018 | 0,006 | 0,021 | -0,008 | 0,015 |
| 53 | 3200 | 66 | 39 | 34 | 64 | 0,021 | 0,006 | 0,021 | -0,008 | 0,015 |
| 54 | 3300 | 45 | 31 | 34 | 30 | 0,014 | 0,006 | 0,021 | -0,008 | 0,015 |
| 55 | 2300 | 43 | 34 | 34 | 10 | 0,019 | 0,008 | 0,022 | -0,007 | 0,015 |
| 56 | 3400 | 40 | 33 | 28 | 46 | 0,012 | 0,006 | 0,021 | -0,009 | 0,015 |
| 57 | 2500 | 30 | 43 | 25 | 38 | 0,012 | 0,007 | 0,022 | -0,008 | 0,015 |
| 58 | 3250 | 35 | 46 | 12 | 64 | 0,011 | 0,006 | 0,021 | -0,008 | 0,015 |
| 59 | 2950 | 31 | 42 | 65 | 34 | 0,011 | 0,007 | 0,021 | -0,008 | 0,015 |
| 60 | 4100 | 32 | 48 | 65 | 37 | 0,008 | 0,006 | 0,020 | -0,009 | 0,015 |
| 61 | 3540 | 45 | 45 | 55 | 34 | 0,013 | 0,006 | 0,021 | -0,009 | 0,015 |
| 62 | 3000 | 55 | 75 | 50 | 31 | 0,018 | 0,007 | 0,021 | -0,008 | 0,015 |
| 63 | 3200 | 51 | 34 | 30 | 37 | 0,016 | 0,006 | 0,021 | -0,008 | 0,015 |
| 64 | 3600 | 70 | 37 | 20 | 61 | 0,019 | 0,006 | 0,021 | -0,009 | 0,015 |
| 65 | 4210 | 64 | 39 | 40 | 61 | 0,015 | 0,006 | 0,020 | -0,009 | 0,015 |
| 66 | 3650 | 33 | 73 | 60 | 64 | 0,009 | 0,006 | 0,021 | -0,009 | 0,015 |
| 67 | 4560 | 44 | 34 | 68 | 97 | 0,010 | 0,005 | 0,020 | -0,009 | 0,015 |
| 68 | 3000 | 48 | 61 | 65 | 37 | 0,016 | 0,007 | 0,021 | -0,008 | 0,015 |
| 69 | 3100 | 63 | 34 | 24 | 61 | 0,020 | 0,006 | 0,021 | -0,008 | 0,015 |
| 70 | 2350 | 38 | 36 | 35 | 64 | 0,016 | 0,007 | 0,022 | -0,007 | 0,015 |
| 71 | 2250 | 49 | 39 | 46 | 91 | 0,022 | 0,008 | 0,022 | -0,007 | 0,015 |
| 72 | 3100 | 75 | 32 | 43 | 37 | 0,024 | 0,006 | 0,021 | -0,008 | 0,015 |
| 73 | 4500 | 45 | 31 | 43 | 91 | 0,010 | 0,005 | 0,020 | -0,009 | 0,015 |
| 74 | 3500 | 51 | 67 | 96 | 92 | 0,015 | 0,006 | 0,021 | -0,009 | 0,015 |
| 75 | 2100 | 31 | 35 | 45 | 90 | 0,015 | 0,008 | 0,023 | -0,007 | 0,015 |
| 76 | 2400 | 42 | 34 | 35 | 34 | 0,018 | 0,007 | 0,022 | -0,007 | 0,015 |
| 77 | 2500 | 29 | 38 | 31 | 31 | 0,012 | 0,007 | 0,022 | -0,008 | 0,015 |
| 78 | 4200 | 78 | 34 | 25 | 34 | 0,019 | 0,006 | 0,020 | -0,009 | 0,015 |
| 79 | 3200 | 66 | 32 | 21 | 41 | 0,021 | 0,006 | 0,021 | -0,008 | 0,015 |
| 80 | 3100 | 25 | 34 | 24 | 67 | 0,008 | 0,006 | 0,021 | -0,008 | 0,015 |

| 81  | 3250 | 36 | 64 | 37 | 49 | 0,011 | 0,006 | 0,021 | -0,008 | 0,015 |
|-----|------|----|----|----|----|-------|-------|-------|--------|-------|
| 82  | 3250 | 63 | 31 | 64 | 10 | 0,019 | 0,006 | 0,021 | -0,008 | 0,015 |
| 83  | 3650 | 43 | 34 | 31 | 13 | 0,012 | 0,006 | 0,021 | -0,009 | 0,015 |
| 84  | 3220 | 59 | 68 | 73 | 40 | 0,018 | 0,006 | 0,021 | -0,008 | 0,015 |
| 85  | 3600 | 37 | 34 | 21 | 43 | 0,010 | 0,006 | 0,021 | -0,009 | 0,015 |
| 86  | 4200 | 49 | 38 | 20 | 47 | 0,012 | 0,006 | 0,020 | -0,009 | 0,015 |
| 87  | 3700 | 56 | 38 | 24 | 76 | 0,015 | 0,006 | 0,021 | -0,009 | 0,015 |
| 88  | 2800 | 53 | 38 | 30 | 56 | 0,019 | 0,007 | 0,022 | -0,008 | 0,015 |
| 89  | 2900 | 34 | 36 | 40 | 50 | 0,012 | 0,007 | 0,021 | -0,008 | 0,015 |
| 90  | 3500 | 34 | 37 | 46 | 33 | 0,010 | 0,006 | 0,021 | -0,009 | 0,015 |
| 91  | 3100 | 51 | 35 | 21 | 39 | 0,016 | 0,006 | 0,021 | -0,008 | 0,015 |
| 92  | 3100 | 43 | 37 | 19 | 53 | 0,014 | 0,006 | 0,021 | -0,008 | 0,015 |
| 93  | 3500 | 62 | 35 | 31 | 56 | 0,018 | 0,006 | 0,021 | -0,009 | 0,015 |
| 94  | 3500 | 61 | 34 | 34 | 56 | 0,017 | 0,006 | 0,021 | -0,009 | 0,015 |
| 95  | 4500 | 49 | 34 | 64 | 49 | 0,011 | 0,005 | 0,020 | -0,009 | 0,015 |
| 96  | 3350 | 43 | 34 | 67 | 64 | 0,013 | 0,006 | 0,021 | -0,009 | 0,015 |
| 97  | 4210 | 49 | 31 | 64 | 67 | 0,012 | 0,006 | 0,020 | -0,009 | 0,015 |
| 98  | 3200 | 43 | 32 | 46 | 18 | 0,013 | 0,006 | 0,021 | -0,008 | 0,015 |
| 99  | 3215 | 45 | 38 | 64 | 20 | 0,014 | 0,006 | 0,021 | -0,008 | 0,015 |
| 100 | 2900 | 31 | 46 | 37 | 29 | 0,011 | 0,007 | 0,021 | -0,008 | 0,015 |
| 101 | 3000 | 45 | 46 | 25 | 23 | 0,015 | 0,007 | 0,021 | -0,008 | 0,015 |
| 102 | 3000 | 60 | 49 | 34 | 29 | 0,020 | 0,007 | 0,021 | -0,008 | 0,015 |

It can be seen in table 4. that the defect control chart or P control chart on wood pellet products is used to determine data that is out of control or exceeds the upper limit and also the lower limit.

b. Control Chart P




### Figure 7. Control Chart P

It can be seen in Figure 7. of the P control Chart that there is data that is out of control or crosses the upper limit and also the lower limit, namely on data 34 with a proportion value of 0.025 and on data 72 with a proportion value of 0.024. This means that the data on the P chart is still not under control so it is necessary to take revision action on the control map.

### c. Control Chart Revision P

Based on the P control map, it is known that there is still data that exceeds the control limits, so corrective action is needed so that no one exceeds the predetermined control limits.



#### Figure 8. Revised P Control Map


It can be seen in Figure 8. that the revised P control chart can be seen that there is no data that is out of control. This means that the data on the P chart is under control so that it can be said that the results of wood pellet production can be said to be good.


7. Causal Diagram (Fishbone)

b.

Fishbone diagram is a visual tool to identify, explore, and graphically describe in detail all the causes associated with a problem [14].

a. High Water Content Fishbone Diagram





It can be seen in Figure 9. explaining the fishbone of high water content defects that the cause and effect diagram or fishbone diagram is a diagram that explains the reason why defects can occur in wood pellets with high water content. There are 3 factors in the high water content fishbone diagram, namely the method factor, which is caused by the production SOP for processing raw materials not being implemented properly. The material factor is caused by very wet wood raw materials and some types of wood have high moisture content. Then the machine factor where the drying machine or dryer works less than optimal so that the wood raw material does not dry optimally before printing.




Figure 10. Density Fishbone Diagram

It can be seen in Figure 10. explaining the density defect fishbone that the cause and effect diagram or fishbone diagram is a diagram that explains the reason why the defect can occur in wood pellets whose density is less. There are 3 factors in the fishbone diagram of less density, namely the method factor, which is caused by the production SOP on mixing raw materials between hardwood and ordinary wood not according to standard. The human factor is caused by negligence of workers in carrying out production SOPs. Then the machine factor where the wood pellet printing machine works less than optimal so that the wood pellets produced do not have maximum density. c. Fishbone Diagram Too Small Shape




Figure 11. Fishbone Diagram of Too Small Shape

It can be seen in Figure 11. explaining the fishbone defect of too small a shape, it is known that the cause and effect diagram or fishbone diagram is a diagram that explains the reason why the defect can occur in wood pellets that are too small. There are 3 factors in the fishbone diagram of too small a shape, namely the method factor, which is caused by the production SOP on mixing raw materials between hardwood and ordinary wood not according to standard. The human factor is caused by negligence of workers in carrying out production SOPs. Then the machine factor where the wood pellet printing machine works less than optimal so that the wood pellets produced have a small size.

## Discussions

Data Processing New Seven Tools Method

New Seven Tools is a tool to map or describe problems, organize data in a diagram so that it is easier to understand and find out the factors that cause these problems[15]. 1. Affinity Diagram





Figure 12. Affinity Diagram

Affinity Diagram is a method that can help collect large amounts of data and organize them into groups or themes based on their relationships [16]. In Figure 12. it is known that there are 4 factors that cause defects in wood pellet products, including


methods, people, machines, and materials. For example, a drying machine that does not work optimally is a problem caused by machine factors.

2. Interrelationship Diagram





Interrelationship diagrams or digraphs, commonly referred to as network diagrams, are tools for analyzing the cause and effect relationships of various complex problems so that it can be known which problems trigger the problem and which problems are the outcome of the problem [17]. In Figure 13. it is known that the cause and effect relationship exists regarding the problem of defects in wood pellet products. For example, worker error is caused by workers who do not mix raw materials according to the SOP. 3. Tree Diagram



### Figure 14. Tree Diagram

Tree diagram is a method used to identify the cause of a problem. Tree diagram analysis is carried out by forming a more structured mindset regarding the causal components associated with problems that have been prioritized [18]. Based on Figure 14. it can be seen that to be able to reduce defects in wood pellet products, several ways can be done on production methods, employee performance, machine performance, and quality of raw materials. The improvement solution is broken down again based on the problems that occur.

| 2 | Matrix Diagram                     |                |                  | $\bigcirc$        | $\frown$         |
|---|------------------------------------|----------------|------------------|-------------------|------------------|
|   | Accordance with SOP                |                |                  |                   |                  |
|   | Worker                             |                |                  |                   |                  |
|   | Error                              |                |                  |                   |                  |
|   |                                    |                |                  |                   |                  |
|   | Machine Not                        |                |                  |                   |                  |
|   | Operating Optimally                |                |                  |                   |                  |
|   | Materials that do not              |                |                  |                   |                  |
|   | meet the standard                  |                |                  |                   |                  |
|   | Factors                            | Tighten SOP    | Improving Worker | Optimizing Engine | Improving Raw    |
|   | Improvement Activity               | Implementation | Performance      | Performance       | Material Quality |
|   | Specific Activity                  | Implementation | Terrormanee      | Tertormanee       | Wateriar Quanty  |
|   | Conducting Training<br>Company SOP |                |                  |                   |                  |
|   |                                    |                |                  |                   |                  |
|   | Conduct Periodic                   |                |                  |                   |                  |
|   | Production Checks                  |                |                  |                   |                  |
|   | Conduct Training                   | $\frown$       |                  | $\bigcirc$        | $\bigcirc$       |
|   | Workers according to field         | $\bigcirc$     |                  |                   | $\bigcirc$       |
| - | Conduct Periodic                   |                |                  |                   |                  |
|   | Performance Monitoring             |                |                  |                   |                  |
|   | Performing Machine                 |                |                  |                   | $\bigcirc$       |
|   | Maintanance Periodically           |                |                  |                   | $\bigcirc$       |
|   | Provide SOP                        |                |                  |                   |                  |
|   | Machine Usage                      |                |                  |                   |                  |
|   | Checking the quality               |                |                  |                   |                  |
|   | of raw materials                   |                |                  |                   |                  |
|   | Controlling Moisture               |                |                  |                   |                  |
|   | Content Raw Materials              |                |                  |                   |                  |

## Figure 15. Matrix Diagram

Figure 15. shows the interrelationships between improvement activities, specific activities, and problem factors. The magnitude of the relationship is depicted by a square symbol which means highly related, a triangle which means related, and a circle which means unrelated. For example, improving worker performance is not related to materials that do not meet standards.

5. Data Analysis Matrix

|                        | Table J. Data Analysis Matrix                           |            |        |
|------------------------|---|------------|--------|
| Primary                | Secondary   | Importance | PT XYZ |
| Tighten SOP            | Conducting Company SOP Training                         | 3          | 2      |
| Implementation         | Conduct Periodic Production Checks                      | 3          | 3      |
| Increase Worker        | Conducting Worker Training in accordance with the field | 3          | 2      |
| Performance            | Conduct Periodic Performance Monitoring                 | 3          | 3      |
| Optimizing Engine      | Perform Maintanance Periodically                        | 3          | 3      |
| Performance            | Provide SOP for Machine Usage                           | 3          | 2      |
| Improve the quality of | Checking the quality of raw materials                   | 3          | 2      |
| raw materials          | Controlling Raw Material Moisture Content               | 3          | 3      |
| Description:           |   |            |        |

Table 5. Data Analysis Matrix

Description:

1 : Not yet done 2 : Done 3 : Often done

Based on table 5. it is known that the comparison between the importance rating and the production process at PT XYZ has a difference of 4 points. This indicates that the wood pellet production process at PT XYZ needs to be improved.

| Table 6. Wood Pellet Manufacturing Process |                    |                        |                       |  |  |  |  |  |
|--|--------------------|------------------------|-----------------------|--|--|--|--|--|
| Type of activity                           | Code<br>activities | Previous<br>activities | Duration<br>(Minutes) |  |  |  |  |  |
| Cutting wood logs into beams               | А                  | -                      | 5                     |  |  |  |  |  |
| Crushing wood blocks into wood chips       | В                  | А                      | 2                     |  |  |  |  |  |
| Crushing wood chips into sawdust           | C                  | В                      | 3                     |  |  |  |  |  |
| Drying sawdust                             | D                  | С                      | 10                    |  |  |  |  |  |
| Turning sawdust into wood pellets          | Ē                  | Ď                      | 5                     |  |  |  |  |  |
| Storing wood pellets                       | F                  | Ē                      | 5                     |  |  |  |  |  |

6. Activity Network Diagram

Based on the production process that occurs in the table above, the activity network diagram is described as follows:




Figure 16. Activity Network Diagram

Activity Network Diagram is a diagram that describes the relationship between various activities and identifies critical activities and critical paths [19]. Based on Figure 16. it is known that there are 6 processes in making wood pellet products per kilogram (kg). Cutting wood logs into blocks with code A duration of 5 minutes, Crushing wood logs into wood chips with code B duration of 2 minutes, Crushing wood chips into sawdust with code C duration of 3 minutes, Drying sawdust with code D duration of 10 minutes, Turning sawdust into wood pellets with code E duration of 5 minutes, Storing wood pellets with code F duration of 5 minutes. So that the total production time is 30 minutes per kilogram (kg).

7. Process Decision Program Chart (PDCP)




Figure 17. Process Decision Program Chart

Description:

= Feasible

 $\bigotimes$  = Difficult to do

Process decision program chart (PDPC) is a diagram used to chart activity plans accompanied by situations that may occur. PDPC is not only used for the final solution to a problem, but can overcome risks that may occur in the future [20]. Based on Figure 17. the corrective action plan is determined to minimize defects in wood pellet products at PT XYZ. The sign (X) in the figure above means that the improvement suggestion is difficult to do, while the sign (O) means it is feasible or practical to do.

## CONCLUSION

Based on the research conducted, it is known that there are 3 types of defects in wood pellet products produced by PT XYZ, namely moisture content that is too high, less density, and shape that is too small. From these three defects, it is known that there are several influencing factors, namely method, human, machine, and material factors. Based on data processing using the Seven Tools method, it is obtained that the percentage of wood pellet product defects at PT XYZ is that the type of shape defect is too small to dominate the number. From a total of 12,782 kg of defective products, 34.24% defects of too high moisture content, 30.50% defects of insufficient density, and 35.26% defects of too small shapes, which are then used as a reference in the improvement analysis.

Through the results of data processing using the New Seven Tools method, the causes of defects that occur in the production of wood pellets are known. The errors that occur are caused by several factors such as method, human, machine, and material factors, such as employees who do not comply with SOPs, lack of machine maintenance, wood raw materials or wood powder that does not meet the standards, worker errors in mixing the composition of wood powder. To prevent errors that can cause defects products can be done by tightening the implementation of the company's SOP, improving worker performance and skills, optimizing machine performance, and improving the quality of the raw materials used.

### ACKNOWLEDGMENT

Thanks to PT XYZ for providing the opportunity, time, information, data, which are needed to conduct research in accordance with the topic to be raised. thanks also to Mrs. Isna as the supervisor and friends who have helped this research.

## REFERENCES

- [1] P. Wisnubroto And A. Rukmana, "Pengendalian Kualitas Produk Dengan Pendekatan Six Sigma Dan Analisis Kaizen Serta New Seven Tools Sebagai Usaha Pengurangan Kecacatan Produk," *J. Teknol.*, Vol. 8, No. 1, Pp. 65–74, 2015.
- [2] D. Diniaty, "Analisis Kecacatan Produk Tiang Listrik Beton Menggunakan Metode Seven Tools Dan New Seven Tools (Studi Kasus: Pt. Kunango Jantan)," J. Tek. Ind. J. Has. Penelit. Dan Karya Ilm. Dalam Bid. Tek. Ind., Vol. 2, No. 2, P. 157, 2016, Doi: 10.24014/Jti.V2i2.5102.
- [3] E. Y. Setyawan, A. Lomi, And C. Saleh, "Penggunaan Wood Pellet Untuk Bahan Bakar Produksi Tahu Di Ukm Kab. Kediri," *J. Apl. Sains Teknol. Nas.*, Vol. 2, No. 2, Pp. 22–28, 2021.
- [4] Y. N. Latifah, P. S. Indhira, I. M. Nabila, And I. Nugraha, "Analisis Pengendalian Kualitas Produk Roti Ud. Xyz Dengan Total Quality Control (Tqc)," *Waluyo Jatmiko Proceeding*, Vol. 15, No. 1, Pp. 180–185, 2022, Doi: 10.33005/Waluyojatmiko.V15i1.41.
- [5] I. Nursyamsi And A. Momon, "Analisa Pengendalian Kualitas Menggunakan Metode Seven Tools Untuk Meminimalkan Return Konsumen Di Pt. Xyz," J. Serambi Eng., Vol. 7, No. 1, Pp. 2701–2708, 2022, Doi: 10.32672/Jse.V7i1.3878.
- [6] Somadi, B. S. Priambodo, And P. R. Okarini, "Evaluasi Kerusakan Barang Dalam Proses Pengiriman Dengan Menggunakan Metode Seven Tools," J. Intech Tek. Ind. Univ. Serang Raya, Vol. 6, No. 1, Pp. 1–11, 2020.
- [7] F. Rozi And A. J. Nugroho, "Upaya Perbaikan Kualitas Produk Batik Di Batik Allussan Menggunakan Metode Six Sigma Dan New Seven Tools," *J. Cakrawala*

*Ilm.*, Vol. 1, No. 11, Pp. 2971–2982, 2022.

- [8] S. M. Wirawati, "Analisis Pengendalian Kualitas Kemasan Botol Plastik Dengan Metode Statistical Proses Control (Spc) Di Pt. Sinar Sosro Kpb Pandeglang," J. Intent, Vol. 2, No. 1, Pp. 94–102, 2019.
- [9] T. P. Matondang And M. M. Ulkhaq, "Aplikasi Seven Tools Untuk Mengurangi Cacat Produk White Body Pada Mesin Roller," J. Sist. Dan Manaj. Ind., Vol. 2, No. 2, P. 59, 2018, Doi: 10.30656/Jsmi.V2i2.681.
- [10] E. Haryanto And I. Novalis, "Analisis Pengendalian Kualitas Produk Bos Rotor Pada Proses Mesin Cnc Lathe Dengan Metode Seven Tools," J. Tek., Vol. 8, No. 1, 2019, Doi: 10.31000/Jt.V8i1.1595.
- [11] D. A. Nurjanah, I. L. Kusminah, A. N. Rachmat, And N. Nabella, "Analisis Penentuan Komponen Kritis Small Excavator Menggunakan Metode Fmea Dan Diagram Pareto," *J. Safety, Heal. Environ. Eng.*, Vol. 1, No. 1, Pp. 7–15, 2024, Doi: 10.33863/Jshee.V1i1.19.
- [12] S. Nazia, Safrizal, And M. Fuad, "Peranan Statistical Quality Control (Sqc) Dalam Pengendalian Kualitas: Studi Literatur," J. Mhs. Akunt. Samudra, Vol. 4, No. 3, Pp. 125–138, 2023, Doi: 10.33059/Jmas.V4i3.8079.
- [13] H. Dewi, Maryam, And D. Sutiyarno, "Analisa Produk Cacat Menggunakan Metode Peta Kendali P Dan Root Cause Analysis," J. Teknol. Pertan., Vol. 7, No. 2, Pp. 10–18, 2018.
- [14] A. Kuswardana, N. Eka, And H. Natsir, "Analisis Penyebab Kecelakaan Kerja Menggunakan Metode Rca (Fishbone Diagram Method And 5 – Why Analysis) Di Pt. Pal Indonesia (Analysis Of The Causes Of Work Accidents Using The Rca Method (Fishbone Diagram Method And 5 - Why Analysis) In Pt. Pal Indon," *Conf. Saf. Eng. Its Appl.*, Vol. 1, No. 1, Pp. 141–146, 2017.
- [15] A. S. P. Albertus, R. Rochmoeljati, And I. Nugraha, "Analisis Kualitas Defect Produk Pupuk Dolomit Dengan Metode New Seven Tools Dan Failure Mode And Effect Analysis (Fmea) Di Pt. Xyz," *Tekmapro*, Vol. 19, No. 2, Pp. 194–205, 2024, Doi: 10.33005/Tekmapro.V19i2.414.
- [16] H. Ilham, B. Wijayanto, And S. P. Rahayu, "Analysis And Design Of User Interface/User Experience With The Design Thinking Method In The Academic Information System Of Jenderal Soedirman University," *J. Tek. Inform.*, Vol. 2, No. 1, Pp. 17–26, 2021, Doi: 10.20884/1.Jutif.2021.2.1.30.
- [17] A. Miftahul Putra And I. Prakoso, "Pengendalian Kualitas Produk Bubble Window Dengan Metode New Seven Tools (Studi Kasus: Pt. X) Bubble Window Product Quality Control With New Seven Tools Method (Case Study: Pt X)," J. Rekayasa Sist. Ind., Vol. 8, Pp. 97–103, 2021.
- [18] D. A. Anggraini And W. Wijaya, "Analisa Kualitas Crude Palm Oil (Cpo) Dan Usulan Perbaikan Menggunakan Metode Tree Diagram Di Pt. Johan Sentosa Bangkinang," J. Surya Tek., Vol. 5, No. 02, Pp. 57–62, 2017, Doi: 10.37859/Jst.V5i02.645.
- [19] Y. Zakariya, M. F. F. Mu'tamar, And K. Hidayat, "Analisis Pengendalian Mutu Produk Air Minum Dalam Kemasan Menggunakan Metode New Seven Tools (Studi Kasus Di Pt. Dea)," *Rekayasa*, Vol. 13, No. 2, Pp. 97–102, 2020, Doi: 10.21107/Rekayasa.V13i2.5453.
- [20] P. T. Ayudia And Y. Helianty, "Perbaikan Proses Produksi Berdasarkan Metode Failure Mode And Effect Analysis Dan Process Decision Program Chart," Pros. Disem., Pp. 1–11, 2023.

(This page is intentionally left blank)